

Ardeshir B. Cursetjee & Sons Ltd.

(SUCCESSORS TO CURSETJEE MUNCHERJEE'S SONS.)
ESTABLISHED 1810.

STEVEDORES, DUBASHES & CONTRACTORS.

GRAPHIC ADDRESS:
"HOUND" BOMBAY

TEL { OFFICE: 20103 & 28543.
DOCK 25914.
6, RAMPART ROW, FORT,

Bombay, 1. 15th May 1952

REF: BAD/CP

Messrs. J. & C. Harrison Ltd.,
71-74, Mark Lane,
London E.C.3.

Dear Sirs,

Tanker "Georgios P"


We are in receipt of your letters of the 6th, 9th and 12th instant and your cable of the 9th reading as under:-

"RYC fifth Pandi not concerned wrote fully
airmail sixth - Harcalo"

We have contacted our Underwriters and told them that according to the Captain, the negligence is due to the Chief Engineer and they will be held responsible for the claim.

"Georgios P" will be sailing today from Port Sudan for Aden for refueling and we hope she will be in Bombay by the 26th instant.

Regarding the second para of your letter of the 12th please take this matter up very energetically with Lloyds and see that we get the requisite permission to trade in the Malacca Straits and South China Seas. We are particularly keen to go to Penang and Singapore as oil is being offered at good freight. If the requisite permission is given to us, Messrs. Lever Brothers indicate that they will be able to give us full quantity of oil for half of July. So please let us know by return if Lloyds are prepared to give us the requisite permission without reducing the draft.




003349-003356-006012

- 2 -

With regard to the second para of your letter of the 6th regarding payment for the Gas Oil and Lubricating Oil at Piraeus, we confirm that Captain Price has not paid for this there as Shell Oil can only be paid for in England, Sterling area.

Yours faithfully,
For ARDESHIR B. CURSETJEE & SONS LTD.,



Managing Director.



© 2020

Lloyd's Register
Foundation

00602