

Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP NAME

"NICOYA"

REPORT

Liv.

No. 152710

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The Liverpool Surveyors report this ship afloat and on account of contact minor damage repairs effected.

Record of 'To be broken-up 10.59' is recorded in the Register Book.

The Liverpool Committee have transmitted the case to London.

IT IS SUBMITTED no further action is necessary.

IN S.R.L. APPENDIX.

Shell plates F.4 (p & s) indented.

Shell plates G.7 and H.8 (s.s) indented.



© 2020⁵⁹

Lloyd's Register
Foundation

003357-003368-0008