

Exam
amply
should
Repair
from 1

Received from Chief Ship Surveyor **24 AUG 1961**

S NAME "ROCKABILL" REPORT Cork No. 9254

standing Conditions of Class: NONE.

Appendix. (As before ~~xxx None~~)

Due: SPECIAL SURVEY (C) became due 4,61. A proposal to carry out a G.E. for postponement of the Special Survey in May 1959 approved 26.4.61 subject to the requirements of a G.E. the period of postponement to be determined on condition of ship as found. Further proposal to defer the above G.E. until June 1961 approved 5.6.61.
of Present Survey: (Afloat and in dry dock)

General Examination as above.

Features:

The Surveyors recommend postponement of the Special Survey until 4,62.

Prim Certificate in order (~~Yes-None~~)

Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: See Committee Minute.

Condition:

SUBMITTED record of 'DS 7,61' be assigned as recommended, but further ACTION be DEFERRED for Special Survey.

DS 7,61

IN S.R.L. APPENDIX.

Some keel plates, etc. aft set up.

Stem plate (s.s.) indented.

Sheerstrake plates Nos. 4 & 5 (p.s.) from aft indented.

IT IS FURTHER SUBMITTED the Surveyors' recommendation that the Special Survey be DEFERRED until 4,62 merits the favourable consideration of the Committee.



Lloyd's Register Foundation

16.8.61

007269-00376-0001