

1  
Sen  
**COPY**

# Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

20th November, 1947.

Dear Sir,

With reference to Glasgow Report No. 71780 on the Steamer "NARVA", I have to point out that the boiler safety valves are below the Rule size and I have therefore to request you will ascertain from the Surveyors, and let me know, whether accumulation tests were carried out with satisfactory results. I shall also be glad if you will furnish the total heating surface of the two superheaters as this is now reflected in the machinery numeral.


At the same time I shall be glad if you will ascertain and let me know the Owners' intentions in regard to the replacing by cocks of the water gauge double shut off valves on the boilers.

Yours faithfully,

Clerk to the  
Classification Committee.

The Secretary,

GLASGOW.



© 2020

Lloyd's Register  
Foundation

003385-003390-0234