

Received from Chief Ship Surveyor 6 JUN 1956

SHIP'S NAME "TEESWOOD" REPORT Lon. No. 133610

Standing Conditions of Class: NONE.

Improvement of Class (B) (~~As before~~ or None)

Location of Present Survey: (Afloat ~~and in dry dock~~)

Examination afloat after grounding.

Recommendation:

SUBMITTED ACTION be DEFERRED for examination  
in dry dock after grounding.

As Now.

INSERT IN S.R.L.  
Drydocking (grounding).



© 2020 *S.P.K.*  
*4-6-56*

Lloyd's Register  
Foundation

003391-003400-0060

Blk (new)

It is to be  
held resp  
Book or c