

7th April, 1959.

two

HULL

64750, 770, 779, 791, 792, 800, 807,
812 - As recommended.

64787 "SPERO" - As recommended, except that in view of the reported condition of the tailshaft, it is considered that a fresh record of TS OG 2.59 should be withheld, pending the further examination recommended.

Postponement of the Special Survey until September, 1959 has now been approved, and I shall be glad if you will inform the Owners accordingly.

64769 "BENNEVIS" - As recommended. I acknowledge receipt of your letter dated 24th March, the contents of which have been noted.

64796 "SOUTHELLA" - As recommended, except that the notation SS Hul. 2.59 has been withheld pending the completion of the Engine Survey, and I shall be glad to learn what arrangements the Owners propose to make to complete this survey.

64777 "RIGOROUS" The contents of this report have been noted. This vessel will be eligible to be classed +LOCAL "Tug" "Bahrein Coasting Service" when a report has been received of the satisfactory condition of the tug on arrival in the service area.

I return herewith the "As Built" Midship Section Plan for amendment, as it would appear that the amendments shown on the approved plan have now been indicated thereon.

TY" 64815 - As recommended.

64804 - As recommended.



© 2020

Lloyd's Register
Foundation

003401-003408-0015