

"SOMMEN"

Helsingborg 1868.

This vessel's refrigerating appliances were constructed under the supervision of the American Bureau in 1945. Classification with Lloyd's Register is desired. The Helsingborg surveyors report they have examined this installation for classification and it is considered to be good and satisfactory, and recommend the notation of Lloyd's RMC 3.48) for temp. -5°F, & S. RMC 3.48) when the survey has been completed.

See also attached endorsement dated 5.4.48.

To complete the survey the cooling down tests require to be carried out and this, it is stated, will be done at an East American port about May, 1948.

It is submitted action be deferred and the New York Office advised. Photographic copies of first entry should be forwarded and the surveyor's attention specially drawn to the specified temperature, vis -5°F, when the cooling down test is being carried out.

Copies should be taken from the 3 attached plans for our records as the owners wish the originals to be returned.

- (1) No. V. 1700 S. 59 - 1 - 3A.
(2) No. V. 1700 S. 16 - 3 - 7.
(3) No. V. 1700 S. 59 - 1 - 4A.

Yhm

15.4.48

*For Mr. Perrie to
write N.Y.*

*8 return to D.O.
for copies*

*Yhm
16.4.48*



© 2021

Lloyd's Register
Foundation

003409-003416-0079

*Copies are being made
now for home records
Yhm. 15.4.48*