

6m.1,37.

9 DEC 1937

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

"GLENGARRIFF"

Rpt.

Bel.

No. 12046

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92*)

The Belfast Surveyors report this vessel placed in dry dock, the bottom cleaned and coated, repairs to shell plating and minor repairs effected.

The existing patent rudder has been removed and a new single plate rudder fitted as per attached plate and correspondence.

It is submitted the vessel appears worthy to remain as classed with record of survey 11,37.

100A1
11,37 Bel.

The Underwriters of Lloyd's Register
be endorsed "Single rudder not
fitted" and this endorsement
entered in the bottom book



© 2021

9.12.37

Lloyd's Register
Foundation

003409-003416-0121