

MEMORANDUM

From : LLOYD'S REGISTER OF SHIPPING, 71, FENCHURCH STREET,
LONDON, E.C.3.

(Ref. R.)

JMC/DET

To: The Surveyor(s) at ISTANBUL

Date: 21st January, 1963.

Vessel's Name: S.S. "HUSEYIN KAPTAN"

QUESTION

With reference to your memorandum of the 31st August, and your Return 3 dated the 4th January, it is concluded that the Steam Pipe Survey has been held at this time, but your confirmation will be appreciated.

M.A.B.

ANSWER

Date:— 23rd January, 1963

The vessel is at Istinye Shipyard temporarily laid up . The vessel was drydocked and damages sustained by Grounding at Burgez (Black Sea) and by fire in Atlantic Ocean surveyed.

It is anticipated that repairs ~~will~~ will be commenced next month when estimates for cost of repairs have been accepted by the Turkish underwriters.

The steam pipe survey will be held at that time.

RECEIVED 23-1-1963
ANS'D _____



© 2021

Lloyd's Register
Foundation

003409-003416-0149