



Lloyd's Register of Shipping,

18¹/₂, Regent Quay,

Aberdeen, 28th September, 1933.



rence

L.O.

Dear Sir,

Replying to your letter of the 27th inst, with reference to the First Entry Report on the "ROSAPENNA", Abn. No. 17462, I beg to state that the 2 inch ceiling as shown on the approved Midship Section, was not fitted to the ship's sides in the cargo holds in this vessel.

The s.s. "PARKNASILLA", No. 32694 in the Register Book, for which the same Midship Section was used, although the dimensions were slightly different, is reported as having no Cargo Battens. This I find is not correct. When I prepared the First Entry, Abn. No. 17181, before leaving for Liverpool last year, it was then not intended to fit this ceiling, which later was decided upon, and in my absence, was not corrected on the Report. I shall be glad, therefore, if you will have these two ships entered in the Register Book as follows:-

"PARKNASILLA" - 2"^{CLOSE} ceiling fitted.

"ROSAPENNA" - Cargo battens not fitted.

I am, Dear Sir,

Yours faithfully,

T. Richardson

The Secretary,
LONDON.



Lloyd's Register
Foundation

003409-003416-0202

