



Lloyd's Register of Shipping,

18¹/₂, Regent Quay,

Aberdeen, 18th November, 1932.

LLOYD'S REGISTER
RECEIVED
19 NOV 1932
Amtd. X
LONDON

Dear Sir,

I duly received your letter of the 16th inst. with reference to Aberdeen Rpt. No. 17182 on the electric fittings of the s.s. "PARKNASILLA", and with regard thereto beg to state that the amperage of the conductor on the accommodation and deck circuit should have been given as 7 amperes, and not 11.5 as reported.

With regard to the navigation circuit, the figure reported includes 7 amperages required for charging the accumulators for the wireless telephony apparatus, which is only necessary for about one hour a day.

I regret that the errors were copied from my preliminary notes instead of the final ones.

I am, Dear Sir,

Yours faithfully,

P. Fitzgerald

The Secretary,
LONDON.



© 2021

Lloyd's Register
Foundation

003409-003416-0212

Referred to the Chief Engineer Surveyor's Dept.

19 NOV 1932

Noted
20/11/32

g.h.



© 2021

Lloyd's Register
Foundation