

Class is subject to

6 - MAR 1961

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

SHIP'S NAME "RUNIC" REPORT MEL No. 18168.

The Surveyor reports some alleged damage sustained to the air preheater of the port main boiler and repairs deferred until the vessel's arrival at New Zealand, this voyage.

With regard to the above damage it is submitted that the class be made subject to the damaged air preheater of the port main boiler being specially examined and dealt with as found necessary upon the vessel's arrival at a New Zealand port, where she is stated to be proceeding.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as recommended.



© 2021

Lloyd's Register
Foundation

3.3.61.

