

-2-

NEWCASTLE-on-TYNE (CONTINUED)

14th August, 1956.

113508 "WIMBLEDON" - As recommended, except that the class of the ship has been continued subject to Nos. 4 and 5 raised quarter deck sheerstrake plates etc., starboard side aft, being dealt with as necessary by the next Special Survey.

LOBE" - 113523 - As recommended. It is concluded that the shell thickness furnished for D Strake, port side aft, is not indicative of the general condition of the plating but only of the locally wasted spot, but I shall be glad to have your confirmation of this.

113527 "GROWLER" - As recommended. It is concluded that the Endorsement of Certificate item relating to indents in the shell plating, port and starboard, may now be deleted in view of the extensive shell repairs effected at this time, but your confirmation of this is desired.

ANKSOME" - 113535 - As recommended.

113531 "PORT FAIRY" - As recommended. It is concluded that you did not make a further examination of the Donkey Boiler so as to qualify for a later date of survey, but I shall be glad to have your confirmation of this.

drill tes

also consid



© 2020

Lloyd's Register
Foundation

003434-003443-0352