

BY AIR MAIL.

7th January, 1958.

COLOMBO.

4098 - As recommended.

4095 "STARLINE MERCHANT" As recommended. I would refer you to my memorandum of the 31st October last, and shall be glad to learn what arrangements are proposed in regard to the Special, Boiler and Screwshaft Surveys. It is concluded that permanent repairs have now been carried out to the damaged shell plating referred to in this report.



© 2021

Lloyd's Register
Foundation

003450 - 003457 - 0065