

COPY.

Lloyd's Register of Shipping.

VII.

No. 4330h.

Port of Sourabaya. Java;

28th of January, 1941.

This is to Certify that

Moh. F. Vrouwea, -----

the undersigned Surveyor to this Society did at the request of the Owners' Representative at this port, hold a survey on board of the Dutch ms. "KOTA INTEN" of BATAVIA, 7211 tons gross. No. 77746 in Lloyd's Register Book 1940/41, on the 16th day of January 1900 and fortyone and subsequent dates, while vessel was lying afloat at this port, in order to ascertain the fitness of the Lower hold Port and Starboard forward deep tanks in Hatch No. 4 for receiving Palm oil in bulk as cargo and report as follows:


The lower hold, port and starboard forward deep tanks in hatch No. 4 have been tested by a head of water as required by the Rules and --- found sound and tight, double bottom tanks under said deep tanks tested with deep tanks empty and found sound and tight. =====

The bilge and ballast connections have been blanked off, and the heating coils fitted, tested and found sound and tight. =====

The above mentioned deep tanks have been finally examined on the twentyfifth day of January this year, and were found clean, free of rust, paint, scale, residue and moisture, and fit for proper carriage of Palm oil in bulk to destination. =====

A copy of this report has been sent to Lloyd's Register of Shipping Office in London. =====

Fee & expenses, as per certificate No: 4330b, viz. F. 260. - "For 9 certificates Nos. 4330b/4330j."



Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."