

S. NAIROU
STERN FR
8/10



© 2020

Lloyd's Register
Foundation

8/16
M.S. STANVAC NAIROBI

Cracked section of stern frame top,
stb'd side

Aug. 15th 1958

S	Rpt. No
10 Aug 1958	Rpt. 8 no 6061
D. and	
SUBJECT:-	



© 2020

Lloyd's Register
Foundation

003458-003465-0287