

NAIROBI
SPERN. FE
8/10



PSIDE2020
Lloyd's Register
Foundation

M.S. STANVAC NAIROBI

Finished repaire by welding cracked section on
stern ~~frame~~ top, port side

Aug. 18, 1958

SS/MS "

TO A COMPANY *Koke Rph & No 6065* Rpt. No

Dated.....

SUBJECT-



© 2020

Lloyd's Register
Foundation

003458-003465-0289