

Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

NAME "STANVAC NAIROBI"

REPORT

H.K.G.

No. 16659

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/92.)

The ship is subject to bottom shell rivets forward being examined and dealt with as necessary at the next drydocking.

A SPECIAL SURVEY (C) became due 9,61 and was commenced at Hong Kong 12,60. A proposal to postpone completion of the Special Survey until 9,62 was approved 8.11.61, subject to a satisfactory report being received from the Surveyors following a General Examination.

The Owners Representatives' visited this Office and handed in some plans of drillings. They were informed in a letter dated 2.2.62 that in the case of this tanker the percentage of deterioration on the deck should not exceed 17%.

The HONG KONG Surveyors report (12,61) ship examined afloat and in dry dock and a General Examination, together with drilling carried out. The deferred items as above were dealt with. A number of Special Survey repairs were recommended. *SS WAS ADVANCED*

In view of the condition of the shell and deck plating as indicated on Report 8 (Dr) this was forwarded to the Ship Research Department for their comments. They state in a memo dated 20.2.62 that in view of the deterioration of the deck and bottom shell the Owners should be strongly recommended to carry out the Special Survey at the earliest opportunity.

In view of the above, it is submitted record of DS 11,61 be assigned, without special conditions, but ACTION be DEFERRED for completion of the Special Survey, and further information and the Owners attention should be drawn to the contents of Ship Research Department memo dated 20.2.62.

DS 11,61 Without.

NOTE: For Portion of Survey Held:- See List in Ship Reports Dept.  
For Special Survey Repairs:- See Hong Kong Report of 12.61.



© 2020

Lloyd's Register  
Foundation

003458-003465-0315

*R.F.C.  
21/12/62*