

COPY

LLOYD'S REGISTER OF SHIPPING



Port HONG KONG.

11th December, 1961.

This is to Certify that I have

Surveyed the Machinery of the M.V. "STANVAC NAIROBI", 11637 tons gross, of London, whilst afloat and also in dry dock at this Port,

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also

that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book C.S. (with date) now, and A.B.S. 12,61, on completion of this survey,

and that her Machinery Classification Record be continued in the Book.

Note : To complete the A.B.S., the safety valves of the exhaust gas boiler remain to be adjusted under steam.

Parts now examined:

(C.S. Items only)

Sea connections.

Main Engine :

- Nos.1, 4 & 7 cylinders, covers, pistons, rods, valves and gears.
- Nos.1 & 4 connecting rods, top ends and guides.
- Nos.1, 4 & 7 crankpins and bearings.
- Nos.7, 8 & 9 journals and bearings.
- No.4 scavenge pump complete.
- Holding down bolts and chocks.

(Signed) J.L. Whittington

Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
CS Continuous Survey of Engines
DBS Donkey Boiler Survey
ES Engine Special Survey
MBS Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
SPS Steam Pipe Survey
TS Tailshaft Survey
TS(CL) Tailshaft Survey—Continuous Liner
TSN Tailshaft renewed
TS(OG) Tailshaft Survey—Oil Gland

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society.

L. 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

© 2020

Lloyd's Register
Foundation


003458-003465-0324

LLOYD'S REGISTER OF SHIPPING

Parts Now Examined For C.S. : (Contn.)

Main Engine

Automatic starting air & non-return valves.
Attached Fresh water and Salt water pumps.
Crankcase relief devices.
Main engine working and manoeuvring.
Auxiliary condenser.

Independent pumps :

Exhaust gas boiler feed pump.
Scotch boiler feed pump in B.R.
Stand-by J.C. water pump (s.s.a.).
Stand-by L.O. pump (p.s.f.).
Cofferdam pump in E.R. (s.s.f.).
General service pump (s.s.).
Condensate air pump.

Both O.F. pressure pumps.

O.F. & diesel oil booster pumps (2).

All three oil refinery pumps on port side.

O.F. transfer pump in E.R. (s.s.f.).

Main pump-room special products/bidge pump.

Fwd. pump-room O.F. transfer pumps (2).

Forepeak & cofferdam pumps (2).

Pumping arrangements.

Upper and lower main F.W. coolers.

Auxiliary Engine F.W. cooler.

P. & S. main L.O. coolers.

P. & S. O.F. heaters.

Both refinery O.F. heaters.

Refinery O.F. cooler.

Independent diesel driven air compressor and its engine.

Boiler daily service tank.

Evaporator, including safety valves tested under ste.

Windlass.


Fire extinguishing arrangements.

Steam engine driving main S.W. circ. pump.

P. & S. auxiliary boiler forced draught fans (E/D).

Auxiliary electrical equipment.

(C.S. Items only)



KEY TO ABBREVIATIONS

AB2 Auxiliary Boiler Survey
CS Continuous Survey of Engines
DS Donkey Boiler Survey
ES Engine Special Survey
MB2 Main Boiler Survey
MES Modified Survey of Oil Engines
OF Fitted for oil fuel (date) or above 120°F

— While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be noted that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any error or omission in any report or certificate issued by the Society or its Surveyors or in any entry in the Register Book or other publication of the Society. Any error or omission in the Register Book or other publication of the Society shall be the responsibility of the Surveyors or other Officers or Agents of the Society.

© 2020

Lloyd's Register Foundation

Has a Survey also been held on Ship? Yes.
If so, is the Report sent now, or when will it be sent? Now.