

STANDARD-VACUUM TRANSPORTATION COMPANY, LIMITED

AFRICA HOUSE

KINGSWAY

LONDON, W. C. 2

FACTORS:

A. F. TRIPP, JR. (U.S.A.)
J. C. CORRIE
A. J. VECSEY (U.S.A.)
J. H. PIESSE
E. C. STABER (U.S.A.)

TELEGRAMS: STANKINWAY WESTCENT LONDON
CABLES & RADIO: STANKINWAY LONDON
TELEX: LDN. 28454
TELEPHONES: HOLBORN 9471-8
CHANCERY 6126-7

November 12th, 1958

In reply please refer to

82(216)-9882

M.S. "STANVAC NAIROBI"

X PPR
The Secretary,
Lloyd's Register of Shipping,
71, Fenchurch Street,
London, E.C.3.

Dear Sir,

We acknowledge with thanks your letter dated 5th November, 1958, with reference to a number of classification requirements for the subject vessel.

It has been noted that it will be necessary to renew the propeller shaft also the low main injection valve during the next drydocking period. We note also that a special examination is required to be made at the same time of the stern frame and the sole piece which have been repaired at previous drydocking periods by electric welding process.

Orders are now being placed for a new propeller shaft also for a new main injection valve, we will arrange for the delivery of these parts to the vessel in time for installation at the next drydocking. According to our present schedule the vessel is expected to carry out annual repairs and drydocking during August 1959.

Yours very truly,

R. A. Baxter

D. W. Evans
Engineer Superintendent.

By. R. A. Baxter

RAB/jh



© 2020

Lloyd's Register
Foundation

003458-003465-0328

CLASSIFICATION

H

Wm

R.A.P.

ЛОНДОН С.С.
КИНСАЙ
ЯВУОХ АСИГА

ОТДЕЛЕНИЕ ПРОДАЖИ И ОБСЛУЖИВАНИЯ



© 2020

Lloyd's Register
Foundation