

Received from Chief Ship Surveyor

30 OCT 1958

SHIP'S NAME  
AR.

"STANVAC NAIROBI"

REPORT

Kob.

No. 6065.

standing Conditions of Class: Subject to the rudder post (E.W. 7,56)  
being specially examined at next drydocking.

Improvement of Certificate ~~XXXXXXXXXX~~ None)

Condition of Present Survey: (Afloat and in dry dock)

Docking; W & T repairs; E.W. repairs to sternframe.

75  
29-10-58

Recommendation: SUBMITTED Record of 'DS 8,58' be assigned as recommended,  
SUBJECT to sternframe at outer (E.W. 7,56 & 8,58) and at solepiece  
(E.W. 8,58) being specially examined next drydocking.

DS 8,58. Subject.  
Amended.

C.S.S. Records Dept.

to note. Sternframe fractures.



© 2020

Lloyd's Register  
Foundation

