

Extract from the Hamburg Classing Letter dated 19th May, 1953.

2324 "STANVAC NAIROBI". As recommended, except that a record of DBS 3,53 has been assigned and that the vessel's class is subject to the sternframe (repaired by electric welding) being specially examined at the next drydocking.

I shall be glad if you will confirm that a notice board indicating the barred speed range has been fitted at the control station, and that the tachometer has been marked accordingly.



© 2020

Lloyd's Register
Foundation

003458-003465-0345