

Received from Chief Ship Surveyor

NAME "RUTH NURMINEN"  
AR.

REPORT

Abn

9 DEC 1958

No. 97.

ding Conditions of Class: None.

ment of Certificate (As before or None)

of Present Survey: ~~x(Afloat and~~ in dry dock)

Docking; Damage (cause not stated) involving shell plate D.3 (p&s);  
Equipment - loss of a bower anchor and 15 fms. of chain cable.

ndation: SUBMITTED record of 'DS 11,58' be assigned SUBJECT to a  
bower anchor and 15 fms. of chain cable being supplied at the  
earliest opportunity and to shell plate D.3 (p & s from fwd.)  
being examined and dealt with as necessary next drydocking.

DS 11,58. Subject.

S.R.L. APPENDIX.

Nos. 3 & 4 plates in 1st below sheer  
(p & s.f.) indented.

275  
11-12-58

© 2020  
C.S.S. Records Dept.



to note.  
RECORDED  
NOV 12 1958  
RECORDS  
DEPT.

Lloyd's Register  
Foundation

003474-003478-0134