

TELEPHONE: GREENOCK 295.

* N.N. "MERCATOR" *

Lloyd's Register of Shipping,

Empire House

N/1
RUTH 14, Cross-shore Street,

Greenock, 4th October, 1920.



LLOYD'S REGISTER
LONDON.
5. OCT 1920

Dear Sir,

Reference

With reference to your letter of 2nd inst.
regarding Greenock Report No. 17706 on the Steamer
"MAUDIE", I beg to state that the rivets in the edges and
butts of strake below sheerstrake, clear of bridge, are:-
Edges (Upper $1\frac{1}{8}$ " Rivets at $4\frac{1}{3}$ " spacing) Butts; 1" Rivets at 4"
(Lower 1" " " $3\frac{5}{8}$ " " } spacing,

and regret that this was not clearly stated on the Report.

I am, Dear Sir,
Yours faithfully,

Robert Dunsmeir

The Secretary,
L O N D O N.



© 2020

Lloyd's Register
Foundation

003474-003478-0180

Referred to the Chief Ship Surveyor.

THM

-5 OCT 1920

[Signature]
6.10.20

(Reversed)

17 October 1920

Memorandum to the Chief Ship Surveyor



© 2020

Lloyd's Register
Foundation

Page 1
TONNAGE
Less Excess