

23 JUL 1957

Received from Chief Ship Surveyor

SHIPS NAME "TASMANIA" REPORT Gen. No. 22462  
GB

Outstanding Conditions of Class: Subject to indented bottom shell plating (p & s) and indented side shell plates H.8 & J.7 (p.s. from aft) and F.6 (p.s. from fwd) being dealt with by completion of the Special Survey.

Notation of 'SS Msl. 2,57' to be assigned on completion of Special Survey - See cable dated 24.5.57. Endorsement of Class (B) (As before ~~or None~~)

Surveys due: SPECIAL SURVEY (C) due 1,57, commenced Pir. 9,56 and subsequently advanced.

Nature of Present Survey: (Afloat and in dry dock)

Docking: Completion of Special Survey: Damage repairs (various causes) and to the deferred items as above: Alterations - conversion to open shelter deck type ship and removal of 3rd deck in Nos. 3 & 4 holds in accordance with approved plans and correspondence.

Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)  
NONE.

Work completed by xx

Recommendation: SUBMITTED NOTATIONS of 'DS 5,57' and 'SS Msl. 2,57' be assigned, without special conditions but with Endorsement of Certificate.

DS 5,57  
SS Msl. 2,57 Without.

ENDORSEMENT OF CERTIFICATE  
Nos. 6, 7, 8, 9 & 10 keel plates indented.

INSERT IN R.B.  
O.S.D.  
N.S.  
AMEND R.B. to -  
1 dk & S dk, 3rd dk in No.1 hold.

PUBLICATIONS DEPT. to note this report with regard to other alterations to the R.B. particulars.

NOTED FOR POSTING

Noted for Header

S.P.K.  
15.7.57



© 2020 Lloyd's Register Foundation