



LLOYD'S REGISTER OF SHIPPING

Handelskade, 1B, Willemstad, Curaçao, N.A.

Telegrams: Register, Curaçao

Telephone: 12384

31st May, 1958.

Attn: Address:
P. Box 121
Ref.S.

RECEIVED

7 JUN 1958

Ans'd *[Signature]*

The Secretary,
London.

Dear Sir:

Replying to your classing letter of 28th February last, dealing with the "ROSA", Rpt.5272, I wish to state that the sheer strake plate (port side) in way of No.1 wing tank has been renewed and mentioned in my report as "main sheer strake port 'H' No.10". Shell plating in way of No.3 port wing tank (leakage) was also dealt with, and referred to in my report as "Bilge strake in way of port side No.3 tank ~~480~~" cropped and part renewed". The cracked and doubled shell plate at forward end of Engine Room (port side) was renewed, and I regret having omitted this from my report.


I should add that this vessel is now laid up and will be sold for scrap.

The delay in replying to your letter is regretted.

Yours very truly,

W.S. Holmes

Surveyor. 003481003494-0162



SR CLASSIFICATION

H

Noted
James
10/15/58

[Handwritten signature]

[Faint, mostly illegible typed text, possibly a shipping manifest or receipt]

[Handwritten signature]
824 JUL 7 3

RECEIVED

1958 JUL 14

Handmade in Millersville, Maryland, U.S.A.

LLOYD'S REGISTER OF SHIPPING



© 2020
Lloyd's Register
Foundation