

by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME

"PYUDAWTHA"

REPORT

Sng

No.

10445

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/02.*)

of Survey ~~COMPLETION-OF~~ SPECIAL SURVEY OF ENGINES-AND-BOILERS

This Survey, due 11,54 ~~to be~~ <sup>now</sup> held ~~now~~

~~completed, and the following repairs carried out (due to~~):-

A stay renewed in the starboard boiler. Main engine HP piston now renewed at Owners' request.



© 2020

It is submitted the vessel is eligible to remain as classed, with notation of BS 10,54 as recommended.

9.12.54.

