

COPY

Lloyd's Register of Shipping.

(UNITED WITH THE BRITISH CORPORATION REGISTER)



No. 6378

Port Shimonoseki

26th November, 1957.

This is to Certify that I have

*Surveyed the S.S. "PRECILA" 5277 tons gross of Panama On 25th
November, 1957 and subsequently, as she lay afloat at Yawata,
on account of reported leakage of shell plate*

*and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report, stating that all repairs
recommended by me have been completed to my satisfaction, and
that I have Recommended that she be continued as now classed
without fresh record of Survey, subject to No. 1 hold port side
shell plate H-16 being specially examined at next drydocking
and dealt with as found necessary and to all other conditions
attached to the vessels class being dealt with as recommended
being fit to carry her usual cargoes.*


A. Imai Zumi

Surveyor to Lloyd's Register.

A. Imai Zumi

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
uted, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
ever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
mittees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

T. B.) 7.56. KOB



Lloyd's Register
Foundation

003495-003502-0184