

28 MAY 1954

Received from Chief Ship Surveyor

SHIP'S NAME

"TRAVELSTAR"

REPORTS

Man.
Smk.

No. 3855
No. 303

Outstanding Conditions of Class: NONE.

ACTION is DEFERRED pending receipt of Smk.Rpt.

Endorsement of Class (B) (As before ~~or None~~)

Location of Present Survey: (Afloat and in dry dock)

Docking: Extensive damage repairs caused by typhoon.

Recommendation:

SUBMITTED record of docking 2,54 be assigned,
with Endorsement (B).

2,54 Smk.

ENDORSEMENT OF CLASS (B) (AMENDED)

2 bower anchors and stream anchor
to submit to the Statutory Test.

Office note: NS 7.4.54

SPK.
26-5-54.



© 2020

Lloyd's Register
Foundation

003503-003512-0056