

Tonnage under
Tonnage Deck....

676.66

CLASS ... freeboard corresponding to a Summer draft (Mid.)

yes

Built at ...

Do. of space or spaces

Length from fore part of stem to after part of stern

FEET.

Launched 5th Aug., 19

TELEPHONE: PACIFIC 5188

TELEGRAPHIC ADDRESS:
"REGISTRAR" VANCOUVER



Lloyd's Register of Shipping

BRITISH COLUMBIA

1519 MARINE BUILDING
VANCOUVER, B.C.

28th October, 1943.

The Secretary,
Lloyd's Register of Shipping,
Wokingham, England.

Dear Sir:

S.S. "FORT LA BAYE"
West Coast Shipbuilders Ltd. - Hull No. 128

With reference to our Interim Certificate B1
attached to Vancouver First Entry Report No.5999 in the case
of the above mentioned ship, it will be noted that the record
of L.M.C. 10,43 was recommended subject to synthetic resin
insulated electrical cables being specially examined before
the end of October 1945.


Since issuing this Certificate we have been
instructed that the Chief Engineer Surveyor has decided that
such cables may be accepted without special reserve and we
shall be pleased if you will kindly disregard the reference
to these cables in our Interim Certificate.

We are, Dear Sir,

Yours faithfully,

For the Surveyors.

RR/A
c.c. Principal Surveyor,
New York.



© 2020

Lloyd's Register
Foundation

003503-003512-0071

Foundation Plate on
Floors

Third Deck, amidships, Angle, [] or []

