

22/11/51

ascertain the general condition of two Paxman
4 type engines which were completely recommissioned
in 1948 under the supervision of the
on the B.P. Register & have been
regularly maintained in storage since arrival
from the broken works.

engines together with adequate spares,
broken into 2 which have been righted
in good order & are considered suitable
installation in a chartered vessel.

at Hull Surveyors Ltd's certificate
above lines.

probable that engines were originally
under LR scheme for tank landing
engines

see 7/8-8

Sms

1/10/51



© 2020

Lloyd's Register
Foundation

003513-003524-0127