

COPY

20th February, 1963.

Dear Sirs,

Motorship "CALGARIA".

Further to the letter of yesterday's date addressed to you by the Society's London Office, the undernoted is a list of items appearing in the Special Reasons List Appendix which do not affect the classification of the ship and may be left to the Owners' initiative:-


1. port main engine No.3 cylinder liner metalock repaired
2. stem plating etc., slightly set over
3. 2nd strake below sheerstrake in way of engine room on the starboard side slightly set in
4. shell plate No.5 in 4th strake below sheerstrake on the port side forward slightly indented.

Yours faithfully,

Secretary to the
Scottish Committee.

Messrs. Donaldson Brothers & Black Ltd.,
14 St. Vincent Place,
GLASGOW, C.1.

P.S. In consequence of the recent Liverpool survey, of which we were unaware in writing you on the 18th February, a fresh docking date of 12,62 has been assigned together with a new record of PTS 12,62 in respect of the port screwshaft survey.



Lloyd's Register
Foundation

003513-003524-0151