

NE NO: AVENUE 5250 (18 LINES)  
ONDON 23124  
ELEGRAHIC ADDRESSES:  
ARMADORES LONDON TELEX  
ARMADORES LONDON-EC 3

Codes:  
BENTLEY'S COMPLETE PHRASE CODE.  
BENTLEY'S SECOND PHRASE CODE.  
SCOTT'S THE BOE CODE.  
THE NEW BOE CODE.

IGHAM-RICHARDSON & CO LTD  
Ship Owners, Ship & Insurance Brokers.  
BROKERS FOR THE SALE, PURCHASE,  
CONSTRUCTION OF STEAMERS, &c

*Armadores House,  
Bury Street,  
London* 3rd April 1963  
E.C.3. AND AT LLOYDS & THE BALTIC.

EF C  
S/ANL/KMR  
EXTENSION No.

IN REPLYING PLEASE  
QUOTE OUR REFERENCE

RECEIVED

3 - APR 1963

The Secretary,  
Lloyd's Register of Shipping,  
71 Fenchurch Street,  
London E.C.3.

BY HAND

Dear Sir,

m.v. "IRINI'S LUCK"

We acknowledge receipt of both your letters of  
the 29th ult. and 2nd inst. and note contents.

As the undersigned explained to you on the  
telephone it is the Owner's wish and intention for the vessel  
to retain her class until arrival at Santander, Spain, where  
after discharging her cargo from Rostock she is to be  
delivered to buyers for breaking up. As the vessel at present  
is at Rostock discharging and according to your letter you  
have no Society's Surveyor there, we suggest as to whether  
it would be possible for you to send your own surveyor from  
London at the expense of the Owners, as it is difficult for  
the vessel after completion of her discharge at Rostock to  
proceed to another neighbouring port for your inspection and  
then come back to Rostock to load for Spain.

We confirm telephone conversation the writer had  
with you this morning and we now await your decision.

Yours faithfully,  
P. WIGHAM-RICHARDSON & CO. LTD.

*A. N. Lykiardopoulos*

(A.N. Lykiardopoulos)  
Manager.

003525-003532-0234



REPORTS

*jsm*



© 2020  
Lloyd's Register  
Foundation

THE NEW 805 CODE  
COLLATE THE 801 CODE  
RENTAL'S SECOND & THIRD CODE  
RENTAL'S COMPLETE 804/805 CODE

80500