

4m, 5, 62

Class is subject to

leaky rivets in starboard boiler inboard furnace mouth
being dealt with by the end of 6.62.

4E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor 16 JUL 1962

SHIP'S NAME.....

K. J. KNUDSEN

REPORT

Bgn

No.

4967


Boiler repairs

The above subject item now dealt with &
to be deleted



It is submitted that this
vessel is eligible to remain

as **CLASSED.** without Subject



© 2020

Lloyd's Register
Foundation

003525-003532-0304