



# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

KIEL, Holstenbrücke 2, 3rd floor

Telegrams: Lloydsregister, Kiel

Telephone: No. 4 12 30

Reference:  
993/H/F.

**RECEIVED**

22nd June, 1954

**25 JUN 1954**

**Ans'd.....**

Dear Sir,

K.J. "KNUDSEN"

We forward herewith Rpts. 4b, 8 and 9, and Certs. B and B 1 in the case of the above ship.

Plans Nos. SKR 1 and K.J.K. 4 - engine foundation are attached.

Photostat copies of Copenhagen certificates for the main engine are forwarded as follows:

1. No. 580 - engine No. 5220
2. " 9917 - crankshaft - three throw
3. " 9918 - crankshaft - two throw
4. " 2393 - thrust shaft
5. " 9925 - intermediate shaft.

Fees as follows should be charged to the Owners:

<i>im 29/6</i> <i>all for</i>	No. SK 361	
Special Survey +	£ { 93.10. 0 ✓	
Re-engining	{ 40. 0. 0 ✓	
Expenses	{ 5.12. 0 ✓	
Fbd. renewal survey	17.10. 0 ✓	
Part LMC	24. 0. 0 ✓	
DBS	10. 0. 0 ✓	
TS	5. 0. 0 ✓	
Electr. survey	18.15. 0 ✓	
Wear & tear repairs	20. 0. 0 ✓	
Installation of new mchy.	67.10. 0 ✓	
Repairs to new mchy.	10.10. 0 ✓	
Expenses	10. 8. 0 ✓	

LESS FULL FEE BY 40% last SS. 9.5.2

*last bgn 30/6/54*

Photostat copy of the original freeboard report is returned herewith.

The Secretary,  
London

Yours faithfully,

*R. E. Hunter*  
For the Surveyors.

© 2020

Lloyd's Register  
Foundation

003525-003532-0319

ACCOUNTS  
ADMIN/SM.

R.A.F.



© 2020

Lloyd's Register  
Foundation