

SO BIRMINGHAM.

RECEIVED Cable from Port of Spain communicated

Mr Wilson Gurnes who state that
no repairs possible Port of Spain
Gurnes have now instructed Captain to
proceed carefully in ballast to Gaberton.



25/3/50.

Lloyd's Register
Foundation

003534-003540-0032.1