

ESSO BIRMINGHAM.

Mr Wilson Anglo American
informed that Master had
reported from barapeto a
oil fracture 7 ft. (about 3 ft 5)
to 7 start wing tank, about
t about forward end of tank.

Bureau have phoned their N.Y.
office requesting them to consult
office with a view to ^{arranging} immediate
my.



© 2021

RM

Lloyd's Register
Foundation

21/3

pm

003534-003540-0035