

30 JUN 1959

Received from Chief Ship Surveyor

SHIP'S NAME "SUVA BREEZE" REPORT Smk. No. 940

Outstanding Conditions of Class: NONE.

R.L. — Appendix. (~~As before~~ None)

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs to fractured deck plate (H.W.damage).

Recommendation: SUBJECT to fractured and doubled upper deck plate between frames 68-69 (s.s.) being permanently repaired at Hong Kong.

As Now. Subject

NOTE: There is a possibility of the ship being sold for breaking up on reaching Hong Kong.



C.S.S. Records Dept. to note.

© 2021

Lloyd's Register Foundation

Handwritten signature and date 30/6/59

003534-005540-0254