

COPY FOR LONDON

Lloyd's Register of Shipping

UNITED WITH THE BRITISH CORPORATION REGISTER



Port SYDNEY. N.S.W.

22nd December, 1954.

This is to Certify that I have

surveyed the S.S. "RONA"

6341 tons gross of Sydney,

for structural alterations and for examination in dry dock,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, and

that I have **Recommended** that she be continued as now classed with record of Docking Survey 11,54 subject to wing tanks in No. 2 hold not being used for liquid cargoes until satisfactorily tested to fractured hawse pipe (s.s.) being renewed by next S.S. and to permanent repairs being effected to Casing Top by next S.S.

being fit to carry dry and perishable cargoes and to carry molasses in cantilever framed topside tanks and in side tanks in Nos. 3 and 4 holds.

(Cargo battens not fitted in shelter tween decks.)

2 + 3

(Sgd.) T. Nell

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any liability or is to be held responsible for any inaccuracy in any report or certificate issued by the Society, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.