

4 MAR 1958

4 MAR 1958

4 MAR 1958


LATIRUS

The shell and deck have been drilled in way of Nos. 1 and 4 tanks. (Tanks numbered from for'd). It will be necessary to drill the shell and deck in the after well (say No. 6 or 7 tank) before the completion of the special survey.

As regards the reported shell and deck drillings, those in way of No.4 tank are considered to be satisfactory, as is also the shell in way of No.1 tank. Two strakes of deck plating in way of No.1 tank should be renewed (B strake port and starboard is suggested).

It is presumed the scantlings of the internal structure will be dealt with by the Reports Department.

4 MAR 1958



3rd March, 1958.



© 2020

Lloyd's Register  
Foundation

003581-003590-0114