

COPY.

United with the British Corporation Register.

Lloyd's Register of Shipping.



NOV 1958

The main engine tested working and manoverring
 Windlass tested working.
 Steering gear tested working.
 Donkey Boiler examined under steam.
 Electrical circuits megger tested.
 Auxiliaries generally examined externally.

Port LONDON
 4th November, 1958.

The machinery as now seen is considered to be in
 general condition for the purpose referred to overleaf.

This is to Certify that I have

surveyed the Boiler and machinery of the M.V. "LATIRUS" 6476 tons
 gross of London, on the 30th October, 1958 and subsequently, whilst
 the vessel was afloat at anchorage in the River Blackwater, for
 the purpose of ascertaining the general condition of the machinery
 for a contemplated voyage to Rotterdam and the return voyage to
 the River Blackwater as an unclassed vessel,

and that I have transmitted to the Committee of Lloyd's Register

Shipping, London, a Report, as on the other side, stating

that all repairs recommended by me have been completed to

my satisfaction.

This vessel has notation in the Register Book of
 "Laid up - Special Survey and Repairs incomplete."

signed: T.A. ORDE,

Surveyor to Lloyd's Register.

P.P. P.H.W. EVANS

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to
 be noted that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for
 any error or judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other
 members of the Society."



COPY

Lloyd's Register of Shipping
United with the British Corporation Registrar

NOW DONE:-

- The main engine tested working and manouervring at the and
- Windlass tested working.
- Steering gear tested working.
- Donkey Boiler examined under steam.
- Electrical circuits megger tested.
- Auxiliary machinery generally examined externally.

The machinery as now seen is considered to be in satisfi
general condition for the purpose referred to overleaf.

This is to Certify that I have

Surveyed the Boiler and machinery of the M.V. "LATIRUS" 6475 tons
of London, on the 5th October, 1928 and subsequently, whilst
the vessel was afloat at anchorage in the River Blackwater, for
the purpose of ascertaining the general condition of the machinery
for a contemplated voyage to Rotterdam and the return voyage to
the River Blackwater as an unclassified vessel.

and that I have transmitted to the Committee of Lloyd's Register

of Shipping, London, a Report, as on the other side, stating

that all repairs recommended by me have been completed to


This vessel has notation in the Register Book of
"Laid up - Special Survey and Repairs incomplete."

Signed: T.A. O'NEIL

Surveyor to Lloyd's Register.

P.P.F.H.M. EVANS

This certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
The Committee of the Society has endeavoured to ensure that the functions of the Society are properly executed, it is to
be held responsible for any circumstances whatsoever under any circumstances whatever to be held responsible for
that neither the Society nor any member of any of its Committees is under any circumstances whatever to be held responsible for
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of
for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other
of the Society.



Lloyd's Register
Foundation

002281-003590-021

certificate is
the Committe
that neithe
in any re
for any e
nts of the S