

Rosario 4th. June 1963

THIS IS TO CERTIFY THAT I, William C. Roots, the undersigned  
Appointed Acting Engineer Surveyor to Lloyd's Register of  
Shipping did attend on board the vessel:


M/V. "INGER SKOU" - of Danish Flag,  
and of 4430 Registered gross Tons,

whilst vessel was lying alongside at Deposits 25-26 of this port  
on the 3rd. of June 1963 at 1630 hrs. , at the Masters request, to  
carry out a Survey on the Anchor Windlass.-

FOUND: Flat steel bar Link Supports, for Port side hand brake completely  
distorted.- Link Pin bent and fractured.-

RECOMMENDED: Supports and pin to be renewed.-

Attended on board at 0030 hrs. on the 4th of June 1963, finding that  
recommendations had been carried out.- Tested to satisfaction.-

  
Wm. C. Roots.

ACTING ENGINEER SURVEYOR TO  
LLOYD'S REGISTER OF SHIPPING



© 2020

Lloyd's Register  
Foundation

003581-003590-0173