


COPY

LLOYD'S REGISTER OF SHIPPING



Port of TRIESTE

19th May, 1960

part
This is to Certify that I have
Surveyed ~~The~~ Machinery of the M.V. "LEME" 8039 tons gross of Genoa whilst
afloat and in drydock at Trieste on the 13th May, 1960 and subsequently for
C.S. and on account of damage stated to have been caused at Buenos Aires on
the 11th February, 1960

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book
TS (CL) port 5,60 now and C.S. (with date) on completion

and that her Machinery Classification Record be continued in the Book.

Parts now examined:

(C.S. Items only)

Port thrust block shaft and bearings
Diesel generator engine (port aft)
Auxiliary S.W. cooling pump (starbd.)

E. Speri
Engineer Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey	E. Speri
CS	Continuous Survey of Engines	SPS	Steampipe Survey	
DBS	Donkey Boiler Survey	TS	Tailshaft Survey	
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner	
MBS	Main Boiler Survey	TSN	Tailshaft renewed	
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland	
OF	Fitted for oil fuel (date) FP above 150°F.			

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."