

6 APR 1939

Received from Chief Surveyors

to Chief Surveyors

SEL'S NAME

"LUCRINO"

Report

Lon.

No.

106964a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/32.)

re of Survey

When due

The 2nd S.S.No.2 became due 8,38.

The vessel was generally examined in August last in connexion with her change of Ownership and her classification with the Registro Italiano also.

The case received consideration in November last, the Owner stating he was not in a position to give a precise reply regarding the Special Survey and action was then deferred for the present.

The Naples Surveyor now forwards a letter from the Owner stating he has decided to withdraw the vessel from class for economical reasons.

It is submitted the class of this vessel be withdrawn from the Register Book and Three Dots (...) inserted in lieu thereof, indicating withdrawal of class.

Withdraw class

Insert (...)

[Handwritten signature]
6.4.39 *[Handwritten signature]*



© 2020

Lloyd's Register Foundation

003599-003604-0185