

4E

is subject to

Starboard screwshaft being renewed by 3/61.

114 JUN 1961

ived by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

P'S NAME M. I. PARNASSOS

REPORT

Rotterdam

No. 51530.

C.S. closed.

T.S.C. (S) due 2/61, not held.

A.B.S. due 2/61, partly held 8/60, not completed.

Docking, Repair.S&K. The above item dealt with by removal and to be deleted.

Starboard propeller renewed and spare P&amp;P propeller fitted.

Starboard boiler furnaces failed, cracks in furnaces used

8 welded; boiler tested subsequently. The Surveyor recommends  
that the starboard boiler inboard and center furnaces be  
specially examined at next A.B.S.It is submitted that this  
vessel is eligible for THE  
RECORD A.B.S. 8/60.

T.S.C. (S) (N) 3/61,

Subject as recommended  
without condition re (S) screwshaft.

14/6/61.

003599-003604-0336

OPINION OF MACHINERY AND RECOMMENDATIONS The machinery of this vessel is eligible in my  
remain as classed with fresh record of C.S. (with date) on completion of the Survey, fresh