

Received from Chief Ship Surveyor 21 MAY 1957

SHIP NAME "ROCKLEAZE"

REPORT

Brs.

No. 20367

Standing Conditions of Class: Subject to the port hawse pipe being renewed and the shell plating in way dealt with as necessary by next Special Survey.

Endorsement of Class (B) (As before ~~on None~~)
(On Grid)

Place of Present Survey: (~~Afloat~~ and in dry dock)

Docking: Repairs (wear and tear) to shell plate D.3 (p.s.a.)
in way of stokehold.

Recommendation:

SUBMITTED NOTATION of 'DS 4,57' be assigned, subject as above, and to shell plate D.3 (p.s.a.) being specially examined and dealt with as necessary at next drydocking, with Endorsement of Certificate.

DS 4,57 Subject

ENDORSEMENT OF CERTIFICATE
Hawse pipe, lower stem and
stem plating buckled.



© 2020
20557

Lloyd's Register
Foundation

003605-003610-0176