

COPY

Ship's name "CLYDE INVENTOR"

Port

Gls.

No. 94804

The class is subject to deck plating etc. in way of R. skylight and set in shell plates G.14, H.13 & 13 (p.s. from aft), 8, J.8 (s.s. from aft), H.17 (p & s) also to pitted shell plate 14 (s.s. from aft) being specially examined and dealt with as necessary by the Special Survey.

A SPECIAL SURVEY (D) became due 10.62. Postponement until 9.63 was granted 23.7.62 following a satisfactory General Examination.

The Glasgow Surveyors report (10.63), ship examined float for the purpose of issuing a Rpt.10 to allow the ship to proceed to a West German port under tow and in ballast condition.

The ship is considered suitable for a voyage in tow.

The case has been transmitted to London.

In view of the above IT IS SUBMITTED the ship is eligible to proceed in tow to a West German port - class temporarily suspended, subject as above, but ACTION be DEFERRED for Special Survey and pending further information.

SUBJECT

NOTE:- It would appear from a Wreck Report received that the ship has arrived in Germany and will be broken up.

IT IS FURTHER SUBMITTED the Surveyors be advised that in future similar cases this Office should be consulted when undertaking surveys on ships for fitness to proceed in tow as a hulk.

J.F.C.
25.10.63.



© 2020

Lloyd's Register
Foundation