

15 Dec 1936

Received by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

VESSEL'S NAME "ACAVUS" Rpt. Nwc. No. 94452

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/32.)

Nature of Survey \_\_\_\_\_

The Newcastle Surveyors report this vessel placed in dry dock, bottom cleaned and coated.

On account of damage through heavy weather some riveting has been overhauled, particularly in the bottom transverse connections to the fore and after bulkheads in cargo tanks and minor repairs effected.

*The lee bar connections at bulkheads have been reinforced,*

The rudder post of the stern frame found fractured at the outer, temporary repairs have now been effected and the Surveyors recommend the upper part of the sternframe be renewed at the next dry docking.

It is submitted the vessel appears worthy to remain as classed with record of survey 11,36 subject as recommended.

100A1 ) Subject etc.  
11,36 Shl. )  
Carrying petroleum in bulk

(B)

*Spl.*

*[Signature]*  
*[Signature]*  
12-12-36

*W.S.*



© 2021

Lloyd's Register Foundation

003620-003624-0043