

# COPY LLOYD'S REGISTER OF SHIPPING

LONDON

Port of SYDNEY N.S.W.

23rd January, 1962

This is to Certify that I have surveyed the Machinery of the S.S. "ORONTES", 20186 tons gross of this port on the 10th January, 1962, and subsequently for the purpose of Main Boiler Repairs.

and that I will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by me in connection therewith have been carried out to my satisfaction; also that I will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book

and that her Machinery Classification Record be continued in the Book subject to E.M. repairs to No. 4 main boiler back end plate being specially examined at next Main boiler survey, and to all other outstanding conditions of class being dealt with as previously recommended.

Parts now examined:  
(C.S. Items only)

*T. J. McGinness*  
*per W.B.B. Dalton*

Engineer Surveyor to Lloyd's Register.  
(For T.J. McGinness)

### KEY TO ABBREVIATIONS

|     |  |        |                                   |
|-----|--|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tallshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tallshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tallshaft Renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tallshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

