



LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

95, Bothwell Street, Glasgow, C.2

RECEIVED

Telegrams: Register, Glasgow

Telephone: Central 6491 (4 Lines)

9 APR 1953

Am'l

8th April, 1953.

Dear Sir,

Classn(s).

In reply to your letter of the 31st ultimo regarding Greenock Report No. 24866 respecting the Steamer "NADIR" I beg to acquaint you that the Surveyors state that the rivet was renewed in the longitudinal butt strap of the centre boiler as the head of the original rivet was detached from the shank due to excessive 'setting up' or caulking. Rivet heads in the vicinity were tested and found sound.

Yours faithfully,

Alverson

Secretary to the
Scottish Committee.

AR
The Secretary,
LONDON.



© 2020

Lloyd's Register
Foundation

003625-003630-0214

CLASSIFICATION

Hand
Linn

16/4/53

[Handwritten signature]



© 2020

Lloyd's Register
Foundation

STOCK EXCHANGE, BOULEVARD STREET, LONDON, E.C. 5
LLOYD'S REGISTER OF SHIPPING